

MIDWAY MFG. CO.

PHONE: AREA CODE 312 451-1360

CHICAGO PHONE: 992-2250

10750 W. GRAND AVENUE . FRANKLIN PARK, ILL. 60131

SERVICE BULLETIN

GAME: Gun Fight Cocktail Table

SUBJECT: Distorted video caused by rear door fan motor mag-

netic field.

MODIFICATION: Alter mounting of rear door fan motor by rot-

ating the assembly 90 degrees, as shown below.

